


SPECIALTY FASTENERS

0306-

MACHINE BUSHINGS (Zinc)


	I.D. x O.D. x GA.	
A	1/2 x 7/8 x 18 ga	.28¢
B	1/2 x 7/8 x 14 ga	.45
C	9/16 x 15/16 x 18 ga	.45
D	9/16 x 15/16 x 14 ga	.45
E	5/8 x 1 x 18 ga	.45
F	5/8 x 1 x 14 ga	.45
G	3/4 x 1-1/4 x 18 ga	.45
H	3/4 x 1-1/4 x 14 ga	.45
I	7/8 x 1-3/8 x 18 ga	.75
J	1 x 1-1/2 x 18 ga	.75
K	1-1/8 x 1-3/4 x 14 ga	.75
L	1-1/4 x 1-7/8 x 14 ga	.75
M	1-1/2 x 2-1/2 x 14 ga	.90



0310-

LOCK WASHERS - Internal Tooth (Zinc)


A	#2	.08¢
B	#4	.08
C	#6	.08
D	#8	.08
E	#10	.08
F	1/4	.08
G	5/16	.08
H	3/8	.13



0310-

LOCK WASHERS - External Tooth (Zinc)

I	#4	.08¢
J	#6	.08
K	#8	.08
L	#10	.08
M	1/4	.08
N	5/16	.09
O	3/8	.13
P	1/2	.20



0311-

FINISHING WASHERS STEEL (Nickel)

A	#6	.15¢
B	#8	.15
C	#10	.15
D	#12	.15
E	#14	.15
F	#16	.15



0311-

FINISHING WASHERS (Brass)

G	#6	.25¢
H	#8	.25
I	#10	.25
J	#12	.25



0311-

FINISHING WASHERS (Aluminum)


K	#6	.15¢
L	#8	.15
M	#10	.15



0311-

FINISHING WASHERS BRASS (Nickel)

N	#6	.25¢
O	#8	.25
P	#10	.25



0312-

BONDED SEALING WASHERS (Zinc)


A	#8 x 1/2	.16¢
B	#10 x 1/2	.16
C	#12 x 5/8	.25
D	1/4 x 5/8	.25
E	5/16 x 3/4	.40
F	3/8 x 3/4	.40



1535-

BALL BEARINGS

A	5/32	.11¢
B	3/16	.18
C	1/4	.21
D	5/16	.31
E	3/8	.38
F	7/16	.53



1535-

BRONZE SLEEVES

	ID x OD x OAL	
G	1/4 x 5/16 x 3/4	\$2.98
H	1/4 x 3/8 x 1	3.34
I	3/8 x 1/2 x 1	2.98
J	1/2 x 11/16 x 1-1/8	3.78
K	1/2 x 5/8 x 1-1/8	3.34
L	1/2 x 3/4 x 1-1/8	4.97
M	5/8 x 3/4 x 1	3.34
N	5/8 x 3/4 x 1-1/8	3.34
O	3/4 x 1 x 2	5.79



1536-

BRONZE FLANGE BEARINGS

	ID x OD x FLANGE x OAL	
A	1/4 x 3/8 x 15/32 x 1/2	\$3.99
B	3/8 x 1/2 x 5/8 x 1	4.88
C	1/2 x 3/4 x 1 x 1/2	4.70
D	1/2 x 3/4 x 1 x 3/4	5.96
E	5/8 x 3/4 x 1 x 3/4	5.96
F	3/4 x 1 x 1-1/4 x 1	13.01
G	3/4 x 7/8 x 1-1/8 x 3/4	5.33
H	3/4 x 1 x 1-1/4 x 3/4	6.50
I	7/8 x 1 x 1-1/4 x 1	6.50



1537-

BEARINGS

A	3/8 x 1-1/8	\$5.78
B	7/16 x 1-1/8	5.78
C	1/2 x 1-3/8	5.78
D	1/2 x 1-1/8	5.78
E	5/8 x 1-3/8	5.78
F	3/4 x 1-3/8	5.78

